

Capacitor Replacement Kit

This is not a repair kit

Suzo-Happ No. 70-25652-00

IGT Part# 40009003

WINTACT

WP203 F11

Installation Instructions

3 – 6800uF @ 16V	3 – 100uF @ 25V
4 – 2200uF @ 35V	1 – 100uF @ 35V
3 – 47uF @ 35V	2 – 33uF @ 25V
1 – 330uF @ 25V	2 – 10uF @ 50V
4 – 1uF @ 50V	1 – 4.7uF @ 50V
3 – 22uF @ 50V	

Replace all the parts even though many of the original parts seem to be working fine because age, humidity, and temperature cause the value of the electrolytic capacitors to change. Installing all of the parts will assure many more years of trouble free service.

All the capacitors are polarized and can only be inserted in one direction. Watch the markings for polarity on each capacitor.

C39 – 6800uF @ 16V	C99 – 1uF @ 50V
C38 – 6800uF @ 16V	C20 – 22uF @ 50V
C37 – 6800uF @ 16V	C26 – 22uF @ 50V
C45 – 2200uF @ 35V	C25 – 100uF @ 35V
C44 – 2200uF @ 35V	C15 – 33uF @ 25V
C46 – 2200uF @ 35V	C19 – 47uF @ 35V
C47 – 2200uF @ 35V	C4 – 10uF @ 50V
C41 – 47uF @ 35V	C8 – 1uF @ 50V
C48 – 47uF @ 35V	C9 – 1uF @ 50V
C57 – 100uF @ 25V	C11 – 1uF @ 50V
C58 – 330uF @ 25V	C29 – 10uF @ 50V
C52 – 22uF @ 50V	C18 – 33uF @ 25V
C51 – 100uF @ 25V	C24 – 4.7uF @ 50V
C50 – 100uF @ 25V	