

Capacitor Replacement Kit
This is not a repair kit
Suzo-Happ No. 70-25879-00
IGT Part# 40009001
CONDOR
SP1709 MC

Installation Instructions

1 – 220uF @ 25V	1 – 3300uF @ 35V
1 – 220uF @ 35V	1 – 100uF @ 25V
1 – 47uF @ 25V	1 – 1000uF @ 35V
2 – 1uF @ 50V	1 – 2200uF @ 16V
1 – 10uF @ 63V	3 – 470uF @ 25V

Replace all the parts even though many of the original parts seem to be working fine because age, humidity, and temperature cause the value of the electrolytic capacitors to change. Installing all of the parts will assure many more years of trouble free service.

All the capacitors are polarized and can only be inserted in one direction. Watch the markings for polarity on each capacitor.

C17 – 220uF @ 25V	C35 – 3300uF @ 35V
C8 – 220uF @ 35V	C55 – 100uF @ 25V
C10 – 47uF @ 25V	C34 – 1000uF @ 35V
C48 – 1uF @ 50V	C39 – 2200uF @ 16V
C58 – 10uF @ 63V	C33 – 470uF @ 25V
C50 – 1uF @ 50V	C60 – 470uF @ 25V
C53 – 470uF @ 25V	